



GENERAL MILL RULES FOR SDI VISITORS

SDI welcomes you as a visitor to our mill. Safety is our #1 Core Value. In order to provide for a safe tour, we ask that you read the following general rules and guidelines. We ask that at all times you stay with your tour guide. There will be many exciting operations and procedures going on around you as you tour through the mill. Always stay alert, watch your footing, and wear your safety equipment at all times.

MEDICAL/PHYSICAL ISSUES:

1. Anyone with a pacemaker MUST NOT enter the Melt/Cast Building around the LMF. (Located in the southeast corner of Melt/Cast Building), Battery 1 & 2 of the melt deck (behind each furnace shell), and the Submerged Arc Furnace (SAF) in Iron Dynamics.
2. Tour Routes through the Melt/Cast area entail climbing and descending three flights of stairs and an elevated walkway. Persons with physical or medical restrictions are advised to begin their tour at the base of the caster.
3. High heat areas are present throughout the various mills and tour route.

GENERAL SAFETY RULES/GUIDELINES

1. Safety equipment (Hard Hat, Safety Glasses with Side Shields, Orange Flame Retardant Jackets, long pants, and sturdy shoes/boots) must be worn at all times. (Sandals, open toed shoes, high heels, etc are not acceptable footwear).
2. Hearing Protection must be worn while in the mill.
3. Stay with your tour guide at all times. Use handrails when on stairs/walkways.
4. Please stay within the designated walkway and away from restricted areas.
5. Do not touch any equipment or product. There are many moving parts, sharp edges, and hot materials.
6. Visitors must always enter and exit the mill through man doors- never through overhead or equipment doors.
7. Always be aware of and adhere to mill signage.
8. Always look and be aware of overhead crane movement. LOOK UP when entering buildings or passing from bay to bay.
9. Always be aware of your surroundings and activities going on around you.
10. Always be aware of the nearest exit or escape route.
11. Never cross through or go around yellow caution tape or red danger tape.

WE HOPE YOU ENJOY YOUR TOUR. HAVE A SAFE AND ENJOYABLE VISIT WHILE AT OUR FACILITY. Date: _____

Name: _____ Company: _____

WE ASK THAT AT THE END OF YOUR TOUR YOU LEAVE YOUR SAFETY EQUIPMENT WITH YOUR TOUR GUIDE OR WITH A DESIGNATED SDI REPRESENTATIVE.

THANK YOU- SDI MANAGEMENT